



**CUSHING OIL AND GAS FIELD.**

STRUCTURAL CONTOUR LINES OBTAINED FROM ALIDADE ELEVATIONS ON DIRECT CONTACT LINES OF PAWHUSKA LIMESTONE AND LOWER SANDSTONES AS TREATED IN OKLA. GEOL. BULLETIN No. 18. THE STRUCTURE SOUTH OF "DRUMRIGHT" AND "TIGER" WAS OBTAINED FROM WELL RECORDS, ASSUMING AN AVERAGE, UNIFORM THICKNESS BETWEEN THE UPPER PAWHUSKA LIMESTONE AND THE OIL BEARING LAYTON AND WHEELER SANDS. DEVELOPMENT TO 1917.

- Location.
- Abandoned.
- Rig up.
- Oil.
- Drilling.
- Gas.
- ♂ Dry.
- ⊙ Steel Tank.
- Steel Tank under construction.
- Earth Tanks.
- ~ Anticline.
- - - Syncline.
- Fault.

E. G. Gilbert, Dem. 1917.